



# Interagency Aviation Information Bulletin



No. IA IB 18-05

Date: May 25, 2018

Page 1 of 1

**Subject:** Winslow Airport Runway 4/22

**Area of Concern:** All Aviation Operations

**Distribution:** All Aviation Users

**Discussion:** The Winslow Airport recently extended the length of runway 4/22 to **7497'**. The previous runway length precluded use of the Winslow Airtanker Base by some larger airtankers. The tentative FAA publication date for the runway length change is February 2019 and the scheduled update in ForeFlight is late May 2018. As a result, some databases and Apps may not possess the correct runway length. Please ensure you use the new runway length of **7497'** when performing performance calculations.



## ARIZONA

79

---

**WINSLOW-LINDBERGH RGNL** (INW)(KINW) 1 W UTC-7 N35°01.31' W110°43.35' PHOENIX  
 4941 B TPA—5941(1000) NOTAM FILE INW H-4K, L-8G  
 IAP

**RWY 04-22: H7497X150** (ASPH) S-50, D-80, 2S-102, 2D-125  
 MIRL 0.8% up SW  
 RWY 04: Pole.  
 RWY 22: REIL. Thld dspcd 1262'.  
 RWY 11-29: H7100X150 (ASPH) S-60, D-70, 2S-89, 2D-110  
 MIRL 0.4% up NW  
 RWY 11: REIL. VASI(V4L)—GA 3.0° TCH 40'. Tree. Rgt tfc.  
 RWY 29: VASI(V4L)—GA 3.0° TCH 26'. Fence.

**RUNWAY DECLARED DISTANCE INFORMATION**  
 RWY 04: LDA-6237  
 RWY 22: LDA-6237

**SERVICE:** FUEL 100LL, JET A LGTACTIVATE MIRL Rwy 04-22 and  
 Rwy 11-29, REIL Rwy 11 and Rwy 22—CTAF. VASI Rwy 11 and Rwy  
 29 opr continuously.

**AIRPORT REMARKS:** Attended 1400-0100Z. After hrs svc call  
 928-587-2630. Rwy 11-29 outer 35' on each side extremely rough  
 due to vegetation growing in the numerous cracks. Southwest corner of  
 Forest Service ramp clsd. Landing fee for commercial aircraft.  
 Overnight tiedown fee.


**AIRPORT MANAGER:** (928) 289-2422

**WEATHER DATA SOURCES:** ASOS 118.875 (928) 289-0134. HIWAS 112.6 INW.

**COMMUNICATIONS:** CTAF/UNICOM 122.8  
 RCO 122.6 (PRESCOTT RADIO)  
 ALBUQUERQUE CENTER APP/DEP CON 127.675

**AIRSPACE:** CLASS E svc 1100-0600Z other times CLASS G.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE INW.  
 (H) VORTACW 112.6 INW Chan 73 N35°03.70' W110°47.70' 110° 4.3 NM to fld. 4913/14E. HIWAS.




---

### Contact Information:

Jerry Sullivan, Airtanker Base Manager. (928) 289-8810. [jsullivan01@fs.fed.us](mailto:jsullivan01@fs.fed.us)  
 Enrique Pacheco, Asst. Airtanker Base Manager. (928) 289-8812. [espacheco@fs.fed.us](mailto:espacheco@fs.fed.us)

*/s/ Keith Raley*

Chief, Aviation Safety, Training, Program  
Evaluations and Quality Management  
DOI, Office of Aviation Services

*/s/ J. Kent Hamilton*

Branch Chief, Aviation  
Safety Management Systems  
USDA Forest Service